

Antenna Unit/Beacon Unit version 02 New handle

From of serial number 06-02064 Artemis MK5 Antenna Units and Beacon Units have a new handle. The new handle provides a better grip and a grip from all directions.

In addition, the top part and the mounting brackets of the Antenna Unit and the Beacon Unit are spray painted in the same colour as the Bottom Cover. See photos below.



Furthermore, modification A (two 1 nF capacitors between the power supply lines of the antenna heating contacts in the antenna flange and ground) has been standard incorporated.

There are no further changes or modifications between version 01 and version 02 Antenna Units and Beacon Units.

There are no compatibility issues between version 01 and version 02 Antenna Units and Beacon Units.

Distribution

CHL NETHERLANDS B.V. : AEK, AKI, AKO, CWE, HEB, JMH, SHH
Reson B.V. : Technical Department, Sales Department